

Contents

Preface to first edition *xiii*
Preface to second edition *xv*

Chapter 1	The general problem of the stability of microstructure	1
1.1	Introduction	1
1.2	Driving forces for microstructural change – reduction of free energy	6
1.3	Mechanisms of microstructural change – rate controlling step	12
1.4	Quantitative microscopy	27
Chapter 2	Structural instability due to chemical free energy	28
2.1	Instability due to non-uniform solute distribution	28
2.1.1	<i>Thermodynamics of diffusion</i>	28
2.1.2	<i>Modified diffusion equation in the presence of a Kirkendall effect</i>	35
2.1.3	<i>The origin of non-uniform solid solutions – coring or interdendritic segregation</i>	39
2.1.4	<i>Homogenisation of segregation in cast alloys</i>	41
2.1.5	<i>Homogenisation above the non-equilibrium melting temperature</i>	44

2.1.6	<i>Deformation of segregated alloys and its effect on homogenisation</i>	46
2.1.7	<i>Banding in rolled steels</i>	50
2.2	Nucleation of precipitates from supersaturated solid solution	51
2.2.1	<i>Spinodal decomposition</i>	51
2.2.2	<i>Homogeneous nucleation</i>	55
2.2.3	<i>Heterogeneous nucleation</i>	57
2.2.4	<i>The formation of transition phases</i>	60
2.2.5	<i>Trace element effects</i>	63
2.3	Growth of precipitates from supersaturated solid solution	64
2.3.1	<i>Diffusion controlled growth</i>	65
2.3.2	<i>Growth kinetics of grain boundary phases</i>	69
2.3.3	<i>Growth kinetics of Widmanstätten plates</i>	71
2.3.4	<i>Formation of misfit dislocations at interphase boundaries</i>	72
2.4	Second-phase dissolution	77
2.4.1	<i>Diffusion limited dissolution</i>	78
2.4.2	<i>Interface reaction kinetics</i>	80
2.4.3	<i>Precipitate arrays</i>	82
2.4.4	<i>Application of the theory</i>	82
Chapter 3	Highly metastable alloys	84
3.1	Manufacturing methods	85
3.1.1	<i>Rapid solidification</i>	85
3.1.2	<i>Cooling rate and undercooling</i>	87
3.1.3	<i>Condensation, chemical reaction and mechanical disruption</i>	91
3.2	Metastable phase diagrams	94
3.2.1	<i>T₀ lines</i>	94
3.2.2	<i>Submerged phases and transformations</i>	95
3.2.3	<i>Glass transition temperature</i>	99
3.3	Metastable crystalline phases	106
3.3.1	<i>Microcrystalline and nanocrystalline alloys</i>	106
3.3.2	<i>Segregation and supersaturated solid solutions</i>	108
3.3.3	<i>Metastable crystalline and quasicrystalline compounds</i>	114
3.4	Amorphous alloys	121
3.4.1	<i>Formation of amorphous alloys</i>	121

3.4.2	<i>Amorphous alloy structure</i>	126
3.4.3	<i>Atomic mobility and relaxation</i>	132
3.4.4	<i>Crystallisation</i>	138
Chapter 4	Instability due to strain energy	147
4.1	The stored energy of cold work	147
4.1.1	<i>Changes in thermodynamic functions resulting from deformation</i>	147
4.1.2	<i>Measurement of the stored energy of cold work</i>	149
4.1.3	<i>Mechanisms for the storage of energy</i>	151
4.1.4	<i>Variables affecting the stored energy</i>	156
4.2	Recovery	166
4.2.1	<i>The kinetics of recovery</i>	166
4.2.2	<i>Mechanisms of recovery</i>	168
4.3	Recrystallisation	183
4.3.1	<i>Kinetics of recrystallisation</i>	183
4.3.2	<i>Nucleation of recrystallisation</i>	188
4.3.3	<i>Growth of new grains in recrystallisation</i>	192
4.3.4	<i>The recrystallisation of two-phase alloys</i>	202
Chapter 5	Microstructural instability due to interfaces	219
5.1	Introduction	219
5.2	Surface energy and surface tension – σ	220
5.3	Atomic origin of the interfacial free energy	228
5.4	The anisotropy of surface free energy – the σ plot and the Gibbs–Wulff theorem	231
5.4.1	<i>Faceting</i>	237
5.5	Precipitate coarsening: ‘Ostwald ripening’	239
5.5.1	<i>Interfacial free energy</i>	241
5.5.2	<i>The mechanism and kinetics of Ostwald ripening</i>	243
5.5.3	<i>Lattice diffusion – the rate controlling process</i>	251
5.5.4	<i>Interface kinetics: atom transfer across the interface as the rate controlling step</i>	259
5.5.5	<i>Ripening of precipitates on grain boundaries</i>	260
5.5.6	<i>Ripening of precipitates on low angle (dislocation) boundaries</i>	262
5.5.7	<i>Effect of volume fraction on coarsening rates</i>	263
5.5.8	<i>Onset of the coarsening reaction</i>	266

5.5.9	<i>The coarsening reaction in ternary and higher order alloys</i>	270
5.6	Experimental investigations of precipitate coarsening	271
5.6.1	<i>Coarsening of spherical or near spherical precipitates</i>	272
5.6.2	<i>Coarsening of non-spherical precipitates</i>	287
5.6.3	<i>Coarsening kinetics suggesting substructure enhanced diffusion</i>	290
5.6.4	<i>Some applications of the coarsening theory</i>	293
5.6.5	<i>Systems that resist coarsening</i>	295
5.6.6	<i>General conclusions on particle coarsening</i>	297
5.7	Stability of lamellar or fibrous microstructures	298
5.7.1	<i>Rod or fibrous eutectics</i>	298
5.7.2	<i>Lamellar eutectics</i>	300
5.7.3	<i>Experimental observations of coarsening of fibrous eutectic microstructures</i>	302
5.7.4	<i>Observations of coarsening of lamellar eutectics</i>	303
5.7.5	<i>Effect of stress and strain on the stability of eutectic microstructures</i>	304
5.7.6	<i>Discontinuous coarsening of polycrystalline lamellar structures</i>	306
5.8	Microstructural change due to grain boundary energies	307
5.8.1	<i>Normal grain growth</i>	307
5.8.2	<i>Computer modelling of grain growth</i>	316
5.8.3	<i>Experimental results</i>	322
5.8.4	<i>Influence of a dispersed second phase on grain growth</i>	326
5.8.5	<i>Abnormal grain growth</i>	346
5.8.6	<i>Dragging of particles by moving grain boundaries</i>	362
5.9	Dendrite arm coarsening	366
Chapter 6	Other causes of microstructural instability	367
6.1	Introduction	367
6.2	Migration of second-phase inclusions in a temperature gradient	368
6.2.1	<i>Migration of liquid inclusions</i>	371
6.2.2	<i>Interaction of migrating inclusions with grain boundaries</i>	376
6.2.3	<i>Shape stability of migrating liquid inclusions</i>	377
6.2.4	<i>Migration of gas bubbles</i>	378

6.2.5	<i>Migration of two-phase (liquid and vapour) inclusions</i>	380
6.2.6	<i>Migration of solid phases</i>	383
6.2.7	<i>The Soret effect: thermal migration of atoms in a temperature gradient</i>	383
6.3	<i>Migration in a gravitational (acceleration) field</i>	384
6.4	<i>Migration in an electric field – electromigration</i>	385
6.4.1	<i>Migration of grain boundaries under the influence of an electric field</i>	386
6.5	<i>Effect of magnetic fields on metallic microstructure</i>	387
6.5.1	<i>Effect of magnetic fields on the orientation of microstructural features</i>	387
6.5.2	<i>Phase transformations in a magnetic field</i>	390
6.6	<i>Deformation</i>	391
6.6.1	<i>Effect of plastic deformation and fatigue loading on metastable precipitates</i>	391
6.6.2	<i>Enhancement of dislocation recovery by fatigue strain</i>	397
6.6.3	<i>Stress annealing</i>	397
6.6.4	<i>Changes in precipitate distribution during diffusion creep</i>	399
6.7	<i>Precipitate stability under irradiation</i>	401
	<i>References</i>	403
	<i>Index</i>	423