

Contents

<i>Preface</i>	<i>page xi</i>
<i>Notation</i>	<i>xiv</i>
Part I Basic Thermodynamics and Kinetics of Phase Transformations	1
1 Introduction	3
1.1 What Is a Phase Transition?	3
1.2 Atoms and Materials	5
1.3 Pure Elements	6
1.4 Alloys: Unmixing and Ordering	10
1.5 What Is a Phase Transformation?	12
1.6 Brief Review of Thermodynamics and Kinetics	15
Problems	19
2 Temperature–Composition Phase Diagrams	21
2.1 Intuition and Expectations about Alloy Thermodynamics	21
2.2 Free Energy Curves, Solute Conservation, and the Lever Rule	27
2.3 Common Tangent Construction	29
2.4 Continuous Solid Solubility Phase Diagram	32
2.5 Eutectic and Peritectic Phase Diagrams	34
2.6 Ternary Phase Diagrams	37
2.7 Free Energy of a Solid Solution	39
2.8 Unmixing Phase Diagram	44
2.9 Order–Disorder Phase Diagram	47
2.10 Alloy Phase Diagrams	53
Problems	55
3 Diffusion	59
3.1 Processes of Atom Movements in Crystals	60
3.2 The Diffusion Equation	64
3.3 Gaussian and Error Functions in One Dimension	68
3.4 Fourier Series Solutions to the Diffusion Equation	73
3.5 Bessel Functions and Other Special Function Solutions	78
Problems	81

4	Nucleation	83
4.1	Nucleation Phenomena and Terminology	83
4.2	Critical Nucleus	85
4.3	Heterogeneous Nucleation	89
4.4	Free Energy Curves and Nucleation	92
4.5	The Nucleation Rate	95
4.6	Time-Dependent Nucleation	103
4.7	Nucleation in Multicomponent Systems	105
	Problems	107
5	Effects of Diffusion and Nucleation on Phase Transformations	109
5.1	Nonequilibrium Processing of Materials	109
5.2	Alloy Solidification with Suppressed Diffusion in the Solid	112
5.3	Alloy Solidification with Suppressed Diffusion in Both Solid and Liquid	118
5.4	Time, Temperature, and Transformation	120
5.5	Glasses and Liquids	122
5.6	Kinetics near Equilibrium	125
	Problems	129
	Part II The Atomic Origins of Thermodynamics and Kinetics	131
6	Energy	133
6.1	Atomic Schrödinger Equations and Formalism	133
6.2	Molecular Orbital Theory of Diatomic Molecules	135
6.3	Electronic Bands and the Tight-Binding Model	141
6.4	Free and Nearly-Free Electrons	145
6.5	Some Electronic Structures of Materials	149
6.6	Elastic Constants and the Interatomic Potential	155
6.7	Linear Elasticity	159
6.8	Misfitting Particle	163
	Problems	168
7	Entropy	171
7.1	Counting and Entropy	171
7.2	Short-Range Order and the Pair Approximation	176
7.3	Materials Structures and Properties Described by Clusters	179
7.4	Concept of Vibrational Entropy	184
7.5	Phonon Thermodynamics	186
7.6	Bond Proportion Model	189
7.7	Bond-Stiffness-versus-Bond-Length Model	197
	Problems	200

8	Pressure	204
8.1	Materials under Pressure at Low Temperatures	204
8.2	Thermal Pressure, a Step beyond the Harmonic Model	209
8.3	Free Energies and Phase Boundaries under Pressure	211
8.4	Chemical Bonding and Antibonding under Pressure	212
8.5	Pressure-Driven Phase Transitions	215
8.6	Activation Volume	219
	Problems	220
9	Interactions in Microstructures and Constrained Equilibrium	223
9.1	Solid-State Amorphization	224
9.2	Self-Trapping	225
9.3	Thermodynamics of Complex Materials	228
9.4	Partitioning of Energy in Polycrystals and Single Crystals	231
9.5	Coherency Strains in Chemical Unmixing	233
9.6	Coupling between Unmixing Processes	236
9.7	Factoring the Partition Function	243
	Problems	248
10	Atom Movements with the Vacancy Mechanism	250
10.1	Random Walk and Correlations	250
10.2	Correlation Factors for Atoms and Vacancies in Alloys	256
10.3	Phenomena in Alloy Diffusion	260
10.4	Diffusion in a Potential Gradient	268
10.5	Diffusion in a Temperature Gradient	272
10.6	Nonthermodynamic Equilibrium in Driven Systems	274
10.7	Vineyard's Theory of Diffusion	277
	Problems	283
	Part III Types of Phase Transformations	287
11	Thermodynamics and Phase Transitions at Surfaces	289
11.1	Surface Structure	289
11.2	Thermodynamic Roughening Transition	292
11.3	Surface Structure and Kinetics	294
11.4	Energies of Grain Boundaries and Interfaces	297
11.5	Anisotropic Surface Energy	303
11.6	Reactions at Surfaces	306
11.7	Gas Adsorption	311
	Problems	313
12	Melting	318
12.1	Structure and Thermodynamics of Melting	318
12.2	Chemical Trends of Melting	321

12.3	Free Energy of a Solid	323
12.4	Entropy of a Liquid	329
12.5	Thermodynamic Condition for the Melting Temperature	331
12.6	Glass Transition	333
12.7	Two Dimensions	338
	Problems	340
13	Solidification	342
13.1	Solidification Microstructures	343
13.2	Alloy Solidification with Suppressed Diffusion in the Liquid	348
13.3	Constitutional Supercooling	349
13.4	Cellular and Dendritic Microstructures	353
13.5	Dendrite Growth with Solute Segregation	358
13.6	Surface Energy	360
13.7	Developments in Solidification Science	365
	Problems	370
14	Phase Transformations with Interfaces: 1. Microstructure	373
14.1	Guinier–Preston Zones and Precipitation Sequences	373
14.2	Precipitation at Grain Boundaries and Defects	376
14.3	The Eutectoid Transformation and Pearlite	380
14.4	Heat Treatments of Steel	385
14.5	The Kolmogorov–Johnson–Mehl–Avrami Growth Equation	389
14.6	Coarsening	392
	Problems	396
15	Phase Transformations with Interfaces: 2. Energetics and Kinetics	398
15.1	Interface Thermodynamics and Kinetics	398
15.2	Atomistic Model of Interface Motion	403
15.3	Local Nonequilibrium at Fast Interfaces	406
15.4	Elastic Energy and Shape of Growing Plate-Like Precipitates	412
15.5	Elastic Energy and Solute Atoms	414
	Problems	422
16	Spinodal Decomposition	424
16.1	Concentration Fluctuations and the Free Energy of Solution	424
16.2	A Square Gradient Term in the Free Energy	426
16.3	Constrained Minimization of the Free Energy	431
16.4	The Diffusion Equation	434
16.5	Effects of Elastic Energy on Spinodal Decomposition	437
	Problems	440

17 Phase Field Theory	441
17.1 Spatial Distribution of Phases and Interfaces	442
17.2 Order Parameters as Field Quantities	444
17.3 Domain Boundary Structure	448
17.4 Domain Boundary Kinetics	452
Problems	456
18 Method of Concentration Waves and Chemical Ordering	458
18.1 Structure in Real Space and Reciprocal Space	458
18.2 Symmetry and the Star	464
18.3 The Free Energy in k -Space with Concentration Waves	467
18.4 Symmetry Invariance of Free Energy and Landau–Lifshitz Rule for Second-Order Phase Transitions	470
18.5 Thermodynamics of Ordering in the Mean Field Approximation with Long-Range Interactions	474
Problems	479
19 Diffusionless Transformations	482
19.1 Dislocations, Mechanisms, and Twinning	482
19.2 Martensite	488
19.3 Landau Theory of Displacive Phase Transitions	496
19.4 Crystal Instabilities and Phonons	505
Problems	509
20 Thermodynamics of Nanomaterials	511
20.1 Energies of Atoms at Grain Boundaries in Nanocrystals	511
20.2 Gibbs–Thomson Effect	513
20.3 Atomic Structures of Nanocrystals	516
20.4 Electron Energies in Nanomaterials	520
20.5 Entropy of Nanomaterials	524
20.6 Magnetic Nanoparticles	529
Problems	531
21 Magnetic and Electronic Phase Transitions	533
21.1 Overview of Magnetic and Electronic Phase Transitions	534
21.2 Exchange Interactions	539
21.3 Thermodynamics of Ferromagnetism	544
21.4 Spin Waves	548
21.5 Thermodynamics of Antiferromagnetism	551
21.6 Dzyaloshinskii–Moriya Interactions and Skyrmions	553
21.7 Thermodynamics of Ionic Crystals	557

21.8	Ferroelectric Transition	559
21.9	Domains	561
	Problems	563
	<i>Further Reading</i>	565
	<i>References</i>	568
	<i>Index</i>	579
Online Chapters		
Part IV Advanced Topics		589
22	Low-Temperature Analysis of Phase Boundaries	591
23	Statistical Kinetics of Ordering Transformations	604
24	Elastic Energy of Solid Precipitates	622
25	Diffusion, Dissipation, and Inelastic Scattering	631
26	Vibrational Thermodynamics of Materials at High Temperatures	650
27	Cooperative Behavior near a Critical Temperature	677
28	Phase Transitions in Quantum Materials	692
	<i>Further Reading</i>	718
	<i>References</i>	720
	<i>Index</i>	723