

## Contents

<i>Preface</i>	<i>page xv</i>
<b>1 Introduction</b> . . . . .	1
Properties	1
Bonding	2
Types of Materials	3
Crystalline Materials	4
Amorphous Materials	6
Note of Interest	7
Problems	7
<b>2 Phases</b> . . . . .	8
What Is a Phase?	8
Phase Diagrams	8
Lever Law	9
Intermediate Phases	11
Invariant Reactions	12
Effects of Pressure	12
Solid Solutions	13
Grain Structure	14
Grain Size	14
Notes of Interest	15
Problems	16
<b>3 Diffusion</b> . . . . .	18
Fick's First Law	18
Fick's Second Law	18
Solutions of Fick's Second Law	19
Junction of Two Solid Solutions	20
Temperature Dependence of Diffusivity	21

Diffusion in Systems with More than One Phase	22
Notes of Interest	26
Problems	26
<b>4 Mechanical Behavior</b> .....	28
Stress and Strain	28
Elasticity	28
Variation of Young's Modulus	30
Plastic Deformation	31
Strength Dependence on Grain Size	35
Solid Solution Strengthening	36
Cold Work	36
Hardness	38
Slip	38
Notes of Interest	39
Problems	40
<b>5 Mechanical Failure</b> .....	42
Fracture	42
Creep	46
Fatigue	47
Toughness	53
Fracture Mechanics	54
Thermal Shock	55
Delayed Fracture	56
Notes of Interest	57
Problems	58
<b>6 Annealing</b> .....	60
Stages of Annealing	60
Recovery	60
Recrystallization	60
Grain Growth	64
Note of Interest	66
Problems	66
<b>7 Iron and Steel</b> .....	68
Steels	68
Pearlite Formation	69
Alloying Elements in Steel	70
Martensite Formation	71
Nature of Martensite	72
Hardenability	73
Quenching	76

## Contents

vii

Tempering	77
Special Heat Treatments	78
Steel Classification System	79
Low-carbon Steels	80
Stainless Steels	81
Cast Iron	81
Notes of Interest	82
Problems	83
<b>8 Nonferrous Metals . . . . .</b>	<b>85</b>
Aluminum	85
Copper and Copper Alloys	89
Magnesium	91
Titanium	91
Nickel-base Alloys	92
Zinc	93
Notes of Interest	93
Problems	94
<b>9 Casting and Welding . . . . .</b>	<b>95</b>
Casting	95
Macrostructure of Castings	95
Dendrite Formation	96
Liquid-to-solid Shrinkage	96
Solid-state Shrinkage	98
Segregation	98
Gas Evolution	100
Casting Processes	100
Fusion Welding	101
Solid-state Welding	102
Notes of Interest	102
Problems	104
<b>10 Solid Shaping . . . . .</b>	<b>105</b>
Bulk Forming	105
Hot Working vs. Cold Working	106
Sheet Forming	107
Note of Interest	109
Problems	109
<b>11 Polymers . . . . .</b>	<b>110</b>
Thermoplastics	110
Degree of Polymerization	110
Molecular Weight	111

Branching	113
Cross-linking	113
Stereoisomerism	113
Copolymers	114
Molecular Configuration	115
Thermosetting Polymers	115
Addition Polymerization	116
Condensation Polymerization	117
Common Polymers	118
Glass Transition	118
Additives	120
Degradation	121
Properties and Uses of Polymers	121
Epoxies	124
Silicones	124
Notes of Interest	124
Problems	124
<b>12 Polymer Processing . . . . .</b>	<b>125</b>
Cooling	125
Injection Molding	125
Compression Molding	126
Transfer Molding	126
Bulk Extrusion	127
Blown Films and Blow Molding	128
Fiber Drawing and Rolling	128
Thermoforming	128
Foaming	129
Notes of Interest	129
Problems	129
<b>13 Glasses . . . . .</b>	<b>130</b>
Structure of Silicate Glasses	130
Chemical Compositions	131
Bridging and Non-bridging Oxygen Ions	131
Glass Viscosity	132
Thermally Induced Stresses	133
Vycor®	135
Devitrification	136
Photosensitive Glass	136
Other Inorganic Glasses	136
Residual Stresses	137

## Contents

ix

Strength of Glasses	138
Shaping Glass	138
Metallic Glasses	139
Notes of Interest	141
Problems	141
<b>14 Crystalline Ceramics</b> . . . . .	142
Ceramics	142
Slip Systems	142
Ionic Bonding	143
Hardness	143
Porosity	145
Variability of Strength	146
Toughening of Ceramics	147
Growth of Single Crystals	149
Notes of Interest	150
Problems	150
<b>15 Powder Processing</b> . . . . .	151
Powder Compaction	151
Sintering	151
Intermediate and Final Stages of Sintering	153
Loss of Surface Area	154
Particle Size Effect	154
Grain Growth	155
Activated Sintering	156
Liquid Phase Sintering	157
Hot Isostatic Pressing	158
Note of Interest	158
Problems	158
<b>16 Pottery and Concrete</b> . . . . .	160
Clay	160
Processing of Clay Products	160
Forms of Pottery	162
Hydration Reactions	162
Portland Cement	163
Concrete Mixes	164
Asphalt Concrete	165
Notes of Interest	165
Problems	165

<b>17 Composites</b> . . . . .	166
Fiber-reinforced Composites	166
Elastic Behavior of Fiber-reinforced Composites	166
Strength of Fiber-reinforced Composites	170
Volume Fraction Fibers	171
Fiber Length	172
Failures with Discontinuous Fibers	172
Typical Properties	173
Particulate Composites	173
Lamellar Composites	175
Notes of Interest	176
Problems	176
<b>18 Carbon</b> . . . . .	178
Diamond	178
Graphite	179
Carbon Fibers	180
Amorphous Carbon	180
Fullerenes	181
Nanotubes	181
Notes of Interest	182
Problems	183
<b>19 Fibers, Foams, and Porous Materials</b> . . . . .	184
Fibers	184
Fabrication of Porous Foams	185
Morphology of Foams	185
Mechanical Properties of Foams	186
Honeycombs	187
Application of Porous Materials	187
Notes of Interest	187
Problems	188
<b>20 Electrical Properties</b> . . . . .	189
Conductivity	189
Metallic Conduction	190
Ionic Conduction	192
Energy Bands	193
Intrinsic Semiconduction	194
Extrinsic Semiconduction	196
III-V Semiconductors	198
<i>n-p</i> Rectifiers	199
Transistors	200
Dielectric Properties	200

## Contents

xi

Piezoelectric Behavior	203
Notes of Interest	204
Problems	205
<b>21 Optical and Thermal Properties</b> . . . . .	<b>206</b>
Spectrum of Electromagnetic Radiation	206
Index of Refraction	207
Reflectivity	209
Absorption	209
Opacity	210
Luminescence	210
Light-emitting Diodes (LEDs)	211
Photovoltaic Cells	211
Lasers	211
Fiber Optics	211
Thermal Expansion	212
Thermal Conductivity	212
Specific Heats	214
Latent Heats of Transformation	214
Thermocouples	214
Notes of Interest	215
Problems	215
<b>22 Magnetic Materials</b> . . . . .	<b>216</b>
Ferromagnetism	216
Domains	216
Saturation Magnetization	217
Ceramic Magnets	218
The $B$ - $H$ Curve	219
Soft Magnetic Materials	220
Hard Magnetic Materials	220
Curie Temperature	221
Magnetic Memory Storage	221
Notes of Interest	222
Problems	222
<b>23 Corrosion</b> . . . . .	<b>224</b>
Aqueous Corrosion	224
Passivity	227
Corrosion Protection	227
Rust	228
Direct Oxidation	228
Notes of Interest	229
Problems	230

<b>24 Modern Manufacturing Techniques, Surface Treatments, and Recycling . . . . .</b>	<b>231</b>
Two-dimensional Photolithography	231
Photo-stereolithography	232
Laser Beams	232
Electron Beams	233
Electrical Discharge Machining	233
Plasma Coating	233
Ion Implantation	234
Recycling of Metals	234
Recycling Plastics	235
Recycling Glass and Paper	236
Notes of Interest	237
Problems	237
APPENDIX 1: Wood . . . . .	239
Structure	239
Dimensional Changes with Moisture	240
Anisotropy of Properties	242
Plywood	242
Notes of Interest	242
Problems	243
APPENDIX 2: Miller Indices for Planes and Directions . . . . .	244
Planar Indices	244
Direction Indices	244
Families of Planes and Directions	245
Notes of Interest	245
Problem	246
APPENDIX 3: X-ray Diffraction . . . . .	247
Note of Interest	247
Problem	248
APPENDIX 4: Surfaces . . . . .	249
Relation of Surface Energy to Bonding	249
Grain Boundaries	250
Segregation to Surfaces	250
Measurements of Relative Surface Energies	251
Surfaces of Amorphous Materials	252
Note of Interest	252
Problems	253
APPENDIX 5: Dislocations . . . . .	254
Edge and Screw Dislocations	254
Stress Fields	256



Contents	xiii
Note of Interest	257
Problems	257
APPENDIX 6: Avrami Kinetics . . . . .	258
Avrami Kinetics	258
Note of Interest	260
Problems	260
APPENDIX 7: Organic Chemistry . . . . .	261
Bonds	261
Bond Energies	261
Bond Angles	262
Note of Interest	263
Problems	264
APPENDIX 8: Average Molecular Weight . . . . .	265
Molecular Weights	265
Note of Interest	266
Problems	266
APPENDIX 9: Bond Geometry in Compounds . . . . .	267
Coordination	267
Ionic Radii	269
Note of Interest	270
Problems	270
APPENDIX 10: Weibull Analysis . . . . .	271
Weibull Analysis	271
Note of Interest	273
Problem	273
<i>Index</i>	275